

DELPHION

[Log Out](#) [Work Files](#) [Saved Searches](#)

RESEARCH

PRODUCTS

INSIDE DELPHION

My Account

No active trail

SELECTOR

Advanced Search

Search: Quick/Number Boolean Advanced Derwent Help

Derwent Record

View: [Expand Details](#) Go to: [Delphion Integrated View](#)Tools: Add to Work File: [Create new Work File](#)


Add

Derwent Title: **Earth leakage detector**Original Title: ☒ [KR1027869A](#): EARTH LEAKAGE DETECTORAssignee: **HYUNDAI HEAVY IND CO LTD** Non-standard companyInventor: **JUNG G C; KIM D S; KO Y C; LEE S M;**Accession/
Update: **2001-548162 / 200161**IPC Code: **G01R 31/02 ;**Derwent Classes: **S01;**Manual Codes: **S01-G04**(Testing for short circuits, discontinuity and leakage [general])Derwent
Abstract:

([KR1027869A](#)) **Novelty** - An earth leakage detector is provided to prevent damage of system due to leakage accident by determining degree of insulation between a power circuit and a frame ground.

Detailed Description - A voltage detecting and switching noise filtering device(1) prevents error due to noise generated upon operation of a system by filtering a signal voltage inputted and detects voltage between a power circuit and a frame ground. A differential amplifier (2) amplifies the detected voltage from the voltage detecting and switching noise filtering device. A controller(3) compares the voltage from the differential amplifier with predefined reference voltage, determines a leakage current quantity and determines whether the leakage accident happens to control the system.

Images:



Dwg. 1/10

@Family:

PDF Patent Pub. Date Derwent Update Pages Language IPC Code
☒ KR1027869A * 2001-04-06 200161 1 English G01R 31/02
Local appls.: KR1999000039842 Filed:1999-09-16 (99KR-0039842)
.....

Priority Number:

Application Number	Filed	Original Title
KR1999000039842	1999-09-16	EARTH LEAKAGE

Pricing Current charges

Derwent	Boolean	Accession/Number	Advanced
---------	---------	------------------	----------


Data copyright Thomson Derwent 2003



Subscriptions | Web Seminars | Privacy | Terms & Conditions | Site Map | Contact Us | Help
Copyright © 1997-2005 The Thomson Corporation



1/1



1/1

DELPHION

Log Out

Work Files

Saved Searches

RESEARCH

My Account

PRODUCTS

INSIDE DELPHION

SELECTOR

NO ACTIVE TRAIL

Search: Quick/Number Boolean Advanced Derwent Help

The Delphion Integrated View: INPADOC Record

☒ PDF | [More choices...](#)

Tools:

Add to Work File

Create new Work File

Add

View: Jump to:

Top

Go to: Derwent

☒ Email this to a friend

Title: KR1027869A: EARTH LEAKAGE DETECTOR

Derwent Title: Earth leakage detector [Derwent Record]

Country: KR Republic of Korea

Kind: A Examined Patent Application

Inventor: JUNG, GI CHAN; Republic of Korea
KIM, DU SIK; Republic of Korea
KO, YEONG CHEOL; Republic of Korea
LEE, SEONG MOK; Republic of Korea

Assignee: HYUNDAI HEAVY INC. Republic of Korea
[News, Profiles, Stocks and More about this company](#)

Published / Filed: 2001-04-06 / 1999-09-16

Application Number: KR1999000039842


IPC Code: G01R 31/02;

ECLA Code: None

Priority Number: 1999-09- KR1999000039842

Family:

PDF	Publication	Pub. Date	Filed	Title
<input checked="" type="checkbox"/>	KR1027869A	2001-04-06	1999-09-16	EARTH LEAKAGE
1 family members shown above				



Other Abstract None

Info:



Nominate this for the Gallery...



THOMSON

Copyright © 1997-2005 The Thomson Corporation
Subscriptions | Web Seminars | Privacy | Terms & Conditions | Site Map | Contact Us | Help

EARTH LEAKAGE DETECTOR

Patent number: KR2001027869
Publication date: 2001-04-06
Inventor: JUNG GI CHAN [KR]; KIM DU SIK [KR]; KO YEONG
CHEOL [KR]; LEE SEONG MOK [KR]
Applicant: HYUNDAI METAL CO LTD [KR]
Classification:
- **International:** G01R31/02
- **European:**
Application number: KR19990039842 19990916
Priority number(s): KR19990039842 19990916

Abstract not available for

Data supplied from the *esp@cenet* database - Worldwide

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.